



Description: LED Taillight
Part Number: 311117 - 311118 - 311119
Application: 00-06 Toyota Tundra (reg/access cab)



Tools needed
10mm Socket and ratchet



Start by unclipping the harness connector located under the vehicle attached to the bumper.



Remove the two 10mm bolts holding the light in. remove the light by pulling straight out.



After removing the taillight from the vehicle pull the harness straight out.



Bolt the new light back in place and connect the harness located under the vehicle. Test all functions of the light before operating on public highway.

AnzoUSA™ products are covered, by a limited one (1) year warranty, to be free of manufacturer's defects. However, certain AnzoUSA™ product categories have warranty policies which differ from this standard, please contact your representative for detailed category information. Damage due to improper installation or road hazards is not covered. Seller and manufacturers' only obligations shall be to replace the product proven to be defective. Neither seller nor manufacturer shall be liable for any injury, loss or damage, direct or consequential, arising out of the use of or the inability to use the product. Before using, user shall determine the suitability of the product for its intended use, and user assumes all risk and liability whatsoever in connection therewith.